

FIG. 21.—Diagrammatic cross sections in northern Wabaunsee County showing the progressive development of Nemaha anticline on line A-A′ of inset. **A.** Structure after erosional beveling of Mississippian limestones. **B.** Structure at end of Lansing time. **C.** Present structure including post-Cretaceous regional dip. **D.** Present structure drawn with the same vertical and horizontal scale.