


Figure 2

Alternate Site A (AEC 3) Showing Geology and Cultural Features in Parts of Lincoln and Ellsworth Counties, Kansas

Contour interval - 10 feet



EXPLANATION

- | | | | |
|---|--|-----|---------------------------------------|
| | Alluvium and terrace deposits | • | Water well |
| | Greenhorn Limestone and Graneros Shale | S | Spring |
| | Dakota Formation | ◇ | Drilled and abandoned oil or gas well |
| ■ | Communication tower | --- | Electric transmission lines |
| ● | AEC Test Hole #3 | — | Pipeline |
| | | --- | Buried communication cables |

Scale 1:48000

